



Model 9533 – Antimicrobial Vinyl Shower Curtain (White) *BradEX*

Model 9537 – Antimicrobial Shower Curtain (White) *BradEX*

Model 9533 Antimicrobial Vinyl Shower Curtain

Guide Specification

Shower curtain 6 gauge vinyl material with hemmed top edges and aluminum grommets on 6" centers. White only.

Vinyl Shower Curtain Model 9533 is available in widths of 36", 42", 48", 60", or 72" and heights of either 72" or 78". See charts below for dimensional information.

- Model 9533 Shower Curtains have a tolerance of +/- 2" length and +/- 2" width, top edge hemmed.**

9533 Models *BradEX*

Width (mm)	Height (mm)	Overall Dimensions (mm)	# of 9536 Shower Hooks Required (order separately)
36" (914)	72" (1829)	36" x 72" (914 x 1829)	6
42" (1067)	72" (1829)	42" x 72" (1067 x 1829)	7
48" (1219)	72" (1829)	48" x 72" (1219 x 1829)	8
60" (1524)	72" (1829)	60" x 72" (1524 x 1829)	10
72" (1829)	72" (1829)	72" x 72" (1829 x 1829)	12

Model 9537 Antimicrobial Shower Curtain

Guide Specification

Shower curtain is 9-oz. nylon-reinforced antimicrobial PVC vinyl fabric (flameproof, stain resistant, self-deodorizing) and furnished with aluminum grommets on 6" centers. Shower curtain is .014" thick with top edge hemmed. Ideal for hospital applications. Model 9537 is White.

Antimicrobial Shower Curtain Model 9537 is available in widths of 36", 42", 48", 60", or 72" and heights of either 72" or 78". See charts below for dimensional information.

9537 Width Tolerances

Width (mm)	Tolerance
36" (914)	+/- 2"
42" (1067)	+/- 2"
48" (1219)	+/- 2"
60" (1524)	+/- 2"
72" (1829)	+/- 2"

Length tolerance is +/- 2"

9537 Models *BradEX*

Width	Height	Overall Dimensions (mm)	# of 9536 Shower Hooks Required (order separately)
36" (914)	72" (1829)	36" x 72" (914 x 1829)	6
42" (1067)	72" (1829)	42" x 72" (1067 x 1829)	7
48" (1219)	72" (1829)	48" x 72" (1219 x 1829)	8
60" (1524)	72" (1829)	60" x 72" (1524 x 1829)	10
72" (1829)	72" (1829)	72" x 72" (1829 x 1829)	12

Orders composed of products indicated as **BradEX** will be available to ship in three days after receipt of order at the factory. There is no pricing penalty for this service from Bradley.