TEMPLATE T-2600

Effective date: December 10,2021 Supercedes: All Previous


NOT TO SCALE

ROCKWOOD[®]



Experience a safer and more open world

ROCKWOOD 2600 SERIES COORDINATOR



NOTE: Field adjustment of door closers is required after installation of coordinator to insure against doors closing too fast and changing coordinator mechanism. Field adjustment of coordinator override could be needed.

NOTE: INSTALL COORDINATOR BEFORE ANY OTHER HARDWARE, EXCEPT HINGES.

Rockwood Manufacturing Company 300 Main St. Rockwood, PA 15557 www.rockwoodmfg.com 1 800 458 2424 NOTE: Rockwood reserves the right to make product changes and is not responsible for obsolete template errors. To ensure your template is current please visit our website at www.rockwoodmfg.com or call us at 800 458 2424

Copyright © 2019-2021, ASSA ABLOY Accessories and Door Controls Group, Inc. All rights reserved. Reproduction in whole or in part without the express written permission of ASSA ABLOY Accessories and Door Controls Group, Inc. is prohibited. Printed in the U.S.A T-2600 12/21