## 280X DUST PROOF STRIKE FLOOR & THRESHOLD PREP TEMPLATE 6 2 29/32" [73.8] **MORTISE** Ø1 1/4" [31.9] 2 1/4" [57.2] FLOOR MORTISE **FACEPLATE STYLE** (REMOVABLE) 1 7/16" ⊕હ [36.5] **MORTISE** ₢ SPANNER WRENCH #8 x 1" FPHW (2x) W/ PLASTIC ANCHÓR HOLE (2x) Ø3/4" THRESHOLD STYLE [18.8] **PLUNGER** 1/8" [3.2] THRESHOLD. NUT **MORTISE** [25.4] 2 5/16" [58.7] Œ **MORTISE FLOOR FLOOR** Ø1" Ø1" [25.4] [25.4] MORTISE MORTISE STANDARD MORTISED FLOOR MOUNTING OPTIONAL THRESHOLD MOUNTING (FACE PLATE REMOVED) FLOOR MOUNTING: 1. DRILL 1"[25.4] HOLE 2-5/16"[58.7] DEEP IN FLOOR. (USE INSTALLED FLUSHBOLT TO MARK LOCATION FOR THE 1"[25.4] HOLE IN THE FLOOR 2. PLACE STRIKE OVER DRILLED HOLE AND MARK OUTLINE OF FACEPLATE ON THE FLOOR. 3. MORTISE FLOOR 1/8"[6.3] DEEP FOR FACEPLATE. 4. MARK AND DRILL HOLES FOR PLASTIC ANCHORS, INSERT PLUGS INTO THE HOLES. 5. THREAD FACEPLATE ONTO THE BODY OF THE DUST PROOF STRIKE THRESHOLD MOUNTING:

- PROOF STRIKE.
- INSTALL COMPLETE STRIKE INTO THE 1"[25.4] HOLE 6. AND SCECURE FACEPLATE USING (2) #8 SCREWS.
- 2.

- GHOLD MOUNTING:
  USE INSTALLED FLUSHBOLT TO MARK LOCATION FOR
  THE 1"[25.4] HOLE IN THE FLOOR.
  TEMPORARILY LAY THRESHOLD IN PLACE ON THE
  FLOOR AND MARK THE LOCATION FOR THE 1"[25.4]
  HOLE USING INSTALLED FLUSHBOLT.
  DRILL 1"[25.4] HOLE 2-5/16"[58.7] DEEP IN FLOOR.
  DRILL 1"[25.4] HOLE THRU THE THRESHOLD.
  SLIDE DUST PROOF STRIKE THROUGH THE DRILLED
  HOLE IN THE THRESHOLD HOLE AND TIGHTEN USING
  THE SUPPLIED NUT. (TIGHTEN TO A SNUG FIT)
  INSTALL THRESHOLD.

INSTALL THRESHOLD



NOTES: HAGER RESERVES THE RIGHT TO MAKE PART CHANGES AND IS NOT RESPONSIBLE FOR OBSOLETE DREAWING ERRORS. TO ENSURE YOUR DRAWING IS CURRENT VISIT WWW.HAGERCO.COM

**NOT TO SCALE** DIMENSIONS IN [] ARE IN MILLIMETERS

TEMPLATE NO: T280X DRAWING NO: T-TA00179 REV: 03 SHEET 1 OF 1 HAGER COMPANIES 139 Victor Street, St. Louis, MO 63104 - (800) 325-9995 - Fax (800) 782-0149