


Architectural Door Accessories

ASSA ABLOY

Rockwood 2600 Series Coordinator

The global leader in
door opening solutions


NOT TO SCALE







Template T-2600

Effective date: January 1, 2017
Supersedes: All Previous

NOTE: ASSA ABLOY reserves the right to make product changes and is not responsible for obsolete template errors. To ensure your template is current, please visit our website at www.rockwoodmfg.com or call us at 800-458-2424



Housing Length	A	B	C	D
32" (N1648)	27 ¹ / ₂ "	OMIT	31"	32"
42" (NX1648)	37 ¹ / ₂ "	OMIT	41"	42"
52" (1654-1696)	47 ¹ / ₂ "	26"	51"	52"
60" (L16108)	55 ¹ / ₂ "	26"	59"	60"



NOTE: Field adjustment of door closers is required after installation of coordinator to insure against doors closing too fast and changing coordinator mechanism. Field adjustment of coordinator override could be needed.

NOTE: INSTALL COORDINATOR BEFORE ANY OTHER HARDWARE, EXCEPT HINGES.

300 Main Street
Rockwood, Pennsylvania 15557
P: 800.458.2424 | F: 800.922.9212
www.rockwoodmfg.com | orders.rockwood@assaabloy.com

Copyright © 2017, Rockwood Manufacturing Company, an ASSA ABLOY Group company. All rights reserved. Reproduction in whole or in part without the express written permission of Rockwood Manufacturing Company is prohibited.